

TECHNICAL BULLETIN TR-25

DATE: March 23, 2007
 MODEL YEAR: 2005 - later
 ENGINE MODEL: J05
 CHASSIS MODEL: UD1300, UD1400, & 1800CS
 BULLETIN NUMBER: TR-25
 FILE IN THE TRANSMISSION SECTION OF THE TECHNICAL BULLETIN BINDER

TORQUE CONVERTER PILOT HUB LUBRICATION FOR AISIN TRANSMISSION

PURPOSE

Lubrication of the Aisin Transmission torque converter pilot hub during transmission installation.

SERVICE PROCEDURE

Whenever vehicle repair or service procedures require the removal of the Aisin transmission it is recommended to apply a thin film of lubrication to the pilot hub on the torque converter during reassembly. (See Figure 1)

This lubrication will aid in the assembly of the converter pilot hub to the flywheel.

Use a NLGI No.1 Molybdenum-based grease or equivalent.




Figure 1

THE INFORMATION CONTAINED IN THIS BULLETIN SHOULD NOT BE INTERPRETED AS THE BASIS FOR WARRANTY CLAIMS							
FOR THE INDICATED PERSONNEL BELOW, PLEASE READ, INITIAL, AND ROUTE TO THE FOLLOWING:							
X	SERVICE MANAGER	X	WARRANTY MANAGER	X	SERVICE TECHNICIANS INITIAL BELOW:		
X	PARTS MANAGER	X	SHOP FOREMAN				